INSPECTION REPORT

Partial XXX Complete Exploration Inspection Date: 04/15/2003/ Time: 8:30 -13:30
Date of Last Inspection: 03/17/2003

Mine Name: Star Point Mine	County: Carbon	Permit Number: <u>C/007/006</u>		
Permittee and/or Operator's Name: Plateau	Mining Corporation			
Business Address: P.O. Box 30, Helper, Ut	ah 84526			
Company Official(s): Johnny Pappas	Federal Off	ficial(s): None		
State Official(s): Karl R. Houskeeper, Wayne Western, Priscilla Burton				
Weather Conditions: Overcast, Snowing, T				
Type of Mining Activity: Underground XX	X Surface Prep	Plant Other		
Existing Acreage: Permitted 9084 Disturb	ped 213.4 Regraded	Seeded		
Status: Active Reclamation		<u> </u>		

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	[X]	ĹÌ	Ĺĺ	Ĺĺ
3.	TOPSOIL		ĹÌ	Ĺĺ	Ĺĺ
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	\Box		
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]	ĹÌ	Ĺĺ	Ĺĺ
c.	OTHER SEDIMENT CONTROL MEASURES		\Box		\Box
d.	WATER MONITORING	[X]	\Box	[X]	
e.	EFFLUENT LIMITATIONS				
5.	EXPLOSIVES				
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES				
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]		[X]	
8.	NONCOAL WASTE				
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION		\Box		
12.	BACKFILLING AND GRADING				
13.	REVEGETATION				
14.	SUBSIDENCE CONTROL		\Box		
15.	CESSATION OF OPERATIONS				
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING				
b.	DRAINAGE CONTROLS				
17.	OTHER TRANSPORTATION FACILITIES				
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS				
19.	AVS CHECK (4 th Quarter- April, May, June)				
20.	AIR QUALITY PERMIT				
21.	BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER:	C/00=/00/	DATE OF INSPECTION:	0.4/1.7/0000
BERMIT MILWIRER.	C/M07/M06		11/4/15/7003
I LIMITI NOMBLIC.	C/00//000	DATE OF HIST LCTION.	UT/13/4003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

A Phase III Bond release site inspection was held in conjunction with this Partial Inspection. A report of the Bond Release Inspection will be compiled and kept on file for review.

The Bond Release Inspection is the result of a request for Phase III bond release on 5.76 acres. The postmining land use for the 5.76 acres was changed from wildlife and grazing to industrial on September 11, 2002. This land use change allowed two gas wells to be constructed on the site. These two gas wells are currently considered producing wells.

The Permittee has another amendment before the Division to remove 11.77 acres from the permit area. Before this amendment can be approved, the 5.76 acres within the disturbed area boundary must be granted Phase III bond release. The permit reduction amendment will be handled in amendment AM02D.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Fourth quarter 2002 water monitoring is in the EDI website. Water monitoring is current.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

Refuse is still being removed form the surface of the refuse pile and is being hauled to Sunnyside Cogeneration's power plant. Several items were discussed concerning the refuse pile surface and drainage structures. The entire pile needs to be graded during the refuse removal to allow surface drainage to flow in a southeastern direction. There is a culvert located at the southeastern side of the refuse pile that removes any surface drainage from the top of the refuse pile. The surface drainage is collected and routed by the culvert to a treatment pond.

Inspector's Signature:			Date:	April 16, 2003
	Karl R. Houskeeper	#49		-

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Johnny Pappas, Plateau
Price Field office
O:\007006.STP\Compliance\2003\p_0415.doc